

Walking pants - Sizing Information

Maximum Circumference

Measurement Parameter - Outer Perimeter Edge excluding Hips	Small	Medium	Large	Extra Large
Inches	36.0	41.0	46.0	53.0
Cm	90.0	102.5	115.0	132.5
Measurement Parameter - Waist Size Excluding Hips	Small	Medium	Large	Extra Large
Inches	31.0	36.0	41.0	48.0
Cm	77.5	90.0	102.5	120.0

Variance and Tolerance < (less than) 12%

Maximum Waist Size = Should Not Exceed - Patient Waist Size Limit

SWL (Safe Working Load) = 300 Kg or 660 Lbs